

Part No.	Amount Used	FAN.	Price	Code
G-992	1	Fan, complete (without crankshaft sprocket and pin), see footnote *	\$3.50	Stay
G-926	1	Fan hub pulley with bushing and blades	.90	Stead
G-927	1	Fan hub pulley with bushing	.90	Steadfast
	1	$\frac{3}{8}$ " x $\frac{1}{4}$ " flat point headless screw	.05	Steak
	4	Fan blade	.10	Stealer
G-930	1	Fan hub bolt	.15	Steam
485	1	Fan hub bolt nut	.02	Stearine
	1	$\frac{1}{8}$ " lock washer	.01	Stearite
3-927	1	$\frac{3}{8}$ " pipe plug	.05	Steed
G-939	1	Fan bracket	.35	Steeper
	1	Fan bracket stud	.10	Steeple
	1	$\frac{3}{8}$ " cotter pin	.01	Steer
3-929	1	Fan bracket stud set screw	.05	Steerage
405	1	Fan bracket stud set screw nut	.02	Steeve
G-931	1	Fan driving pulley	.80	Stela
G-932	2	Fan driving pulley screw	.05	Stellar
G-933	2	Fan driving pulley screw nut	.02	Stench
G-940	1	Fan belt	.55	Stencil
G-934	1	Gray & Davis crankshaft sprocket	2.10	Step
G-935	1	Crankshaft starting pin	.05	Steppe

*Owners of cars, without fan, will find it necessary to purchase the two above parts (G-934 and G-935), in addition to Fan Complete, in order to install properly.

A. W. T. HORN.

H	1	Horn (complete)	3.50	Sterile
H-1 and 2	1	Horn, including bushing	.75	Sterling
H-3 and 33	1	Horn flange, including name plate	.25	Stern
H-4	8	Flange screws	.05	Stetsa
H-5 and 7	1	Disc, including bushing	.30	Steter
H-6	2	Disc gasket	.10	Stevadore
H-9 and 10	9	Striker screw and nut	.25	Stew
H-11 and 16	1	Horn head with rack tube	.50	Steward
H-12	1	Rack	.40	Sthenic
H-13	1	Rack handle	.25	Stibnite
H-14	1	Rack spring	.10	Stich
H-19 and 20	1	Striker assembled	.50	Sticker
H-23 and 24	1	Pawl and rivet	.18	Stickle
H-27	1	Ratchet, including rivet	.12	Stiff
H-29 and 30	1	Pinion shaft with collar	.20	Stigma
H-31 and 32	1	Pivot screw and nut	.20	Stile

TOOLS.

T-1	1	Hammer	.25	Stiletto
T-2	1	Large wrench	.25	Sull
T-3	1	Small wrench	.20	Sult
T-4	1	Screwdriver	.25	Silted
T-5	1	Pliers	.25	Stim
T-6	1	Oil can	.15	Stimulate
T-7	1	Cold chisel	.10	Sria
T-8m	1	Punch	.10	Stina
T-9	1	Cotter pin puller	.10	Sting
3-840	1	Tire removing iron	.20	Stinger
3-841	1	Tire replacing iron	.20	Stinging

No acknowledgment of order will be made unless we are unable to make prompt shipment

Parts Necessary to Change a METZ "25" Touring Model into a 1916 Roadster (indicated by *)

Part No.	Amount Used	TOP AND CURTAINS.	Price	Code
G-1009	1	Top (complete) with curtains and slip cover	\$25.00	*Tab
G-1010	1	Front bow only	.40	Tabac
G-1011	1	Second bow only	.40	Tablet
G-1012	1	Rear bow only	.40	Taboo
G-1013	1	Bow sockets, right (complete)	2.50	Tac
G-1014	1	Bow sockets, left (complete)	2.50	Tactic
G-1015	1	Top roof	5.00	Tad
G-1016	1	Top side curtain, front right	2.00	Tadpole
G-1017	1	Top side curtain, front left	2.00	Tag
G-1018	1	Top side curtain, rear right	2.00	Taint
G-1019	1	Top side curtain, rear left	2.00	Take
G-1020	1	Top slip cover	4.00	Tales
G-1024	2	Top rest arm (complete)	.45	Tally
G-969	2	Top rest arm only	.30	Tame
3-983e	2	Top rest seat	.10	Tan
485	2	Top rest seat securing nut (nickeled)	.06	Tanner
485a	2	Top rest seat securing nut	.03	Target
	2	Top bow strap	.10	Tarsal

SEAT.

G-1000	1	Seat (complete), less cushion	30.00	*Tart
G-1021	1	Seat bottom (complete)	4.50	Task
G-1001	1	Seat cushion (complete)	8.25	*Tassel
G-1001a	1	Seat cushion top	5.75	Taste
G-1022	1	Seat cushion spring	2.50	Tatter

REAR CHEST.

G-1002	1	Rear chest and cover	14.00	*Tattle
G-1023	1	Rear chest cover	3.00	Tattoo
G-1005	1	Rear chest tail piece	1.75	*Taught
G-1007	1	Rear chest front floor board	1.50	*Taunt
G-1008	1	Rear chest rear floor board	.75	*Taurus

REAR GUARDS.

G-1003	1	Rear guard, right (complete)	3.50	*Tavern
G-1004	1	Rear guard, left (complete)	3.50	*Taw
G-941	1	Rear guard iron front, left (complete)	.55	Taxi
G-941a	1	Rear guard iron front, right (complete)	.55	Tea
G-943	2	Rear guard iron front plate	.15	Teach
G-944	1	Rear guard iron rear, left (complete)	.55	Team
G-944a	1	Rear guard iron rear, right (complete)	.55	Tease
G-947	2	Rear guard iron rear plate	.15	Tear
G-1006	1	Tail lamp bracket	.20	*Tech

No acknowledgment of order will be made unless we are unable to make prompt shipment