

8. Replaced R5 with 20 Kohm

10. Need to add inductance tester (not completed)

